Oil Field Environmental Incident Summary

Responsible Party: Wise Services

Well Operator: HRC OPERATING, LLC
Well Name: FORT BERTHOLD 148-94-33C-28-8H

Field Name: MCGREGORY BUTTES Well File #: 26865

Date Incident: 4/25/2014 Time Incident: 13:30 Facility ID Number:

County: DUNN Twp: 148 Rng: 94 Sec: 33 Qtr: SW SW

Location Description: Constructed Roadway from FORT BERTHOLD 148-94-33C-28-8H (Patterson

Rig #268) location to 1/2 on BIA 17.

Submitted By: Kelly Grimm Received By:

Contact Person: Brian Delaney

P.O. Box: 605 24th Ave SW Watford City, ND 58831

General Land Use: Other - Described Above Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 5 Mile **Distance Nearest Water Well:** 5 Mile

Type of Incident: Other

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine

Other 5 Gallons 5 Gallons 5 gallons

Description of Other Released Contaminant:

Oil Based Mud (Patterson Rig #268) from Tank Riser being transported from FORT BERTHOLD 148-94-33C-28-8H to another HRC location

Inspected: Written Report Received: 11/27/2015 Clean Up Concluded: 4/30/2014

Risk Evaluation:No Immediate risk

Areal Extent:

3"x2650' (~665 sq/ft)

Potential Environmental Impacts:

No threat to surface, ground water or topsoil. Impacts confined to Constructed Roadway.

Action Taken or Planned:

Install plug prior to transport. Material scrapped and drummed up for proper E&P disposal.

Wastes Disposal Location: Taken back to rig in leak proof drum for disposal with other rig E&P

waste

Agencies Involved: None

Updates

Date: 4/28/2014 Status: Reviewed - Assigned to Other Agency Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary this spill occurred within the MHA nation boundaries. Report forwarded to MHA Environmental, BIA, and EPA.